



# CEREC Keyboard Shortcuts

Keyboard Combinations	Program Mode	Effects
<F1>	ALL	HELP PANEL FOR THE AREA IN QUESTION
<F5>	ALL	SCREEN-SAVER: ROTATES THE RESTORATION ON SCREEN
<Ctrl> + <F4>	ALL	EXIT CURRENT PROGRAM
<Ctrl> + <o>	ALL	OPEN FILE
<Ctrl> + <s>	ALL	SAVE FILE
<Ctrl> + <z>	ALL	UNDO LAST ACTION
<Ctrl> + <n>	ALL	OPEN NEW FILE
<Ctrl> + <v>	ALL	PASTE
<Ctrl> + <h>	ALL	Hi-INTENSITY MODEL (GREY-SCALE SCREEN)
<Ctrl> + <r>	ALL	RESET
<Ctrl> + <Alt> + <F8>	ALL	EXTENDED COLOR SCALE
<Alt> + <r>	ALL	ACCESS RESTORE MENU
<Alt> + <d>	ALL	ACCESS DESIGN MENU
<Alt> + <t>	ALL	ACCESS SETTING MENU
<Alt> + <w>	ALL	ACCESS WINDOWS MENU
<Alt> + <?>	ALL	ACCESS "?" MENU
Hold Right Mouse Click + Move Trackball	ALL	MOVE MODEL AROUND
Hold Left Mouse Click + Move Trackball	ALL	ROTATE MODEL OR RESTOATION
Hold Left Mouse Click + Move Trackball	Using "form" or "drop" tool	APPLY CONTINUOUS CHANGES TO RESTORATION
<Space Bar>	Using "form" or "drop" tool	CHANGE FUNCTIONS AMONG "ADD", "SUBTRACT", "SMOOTH"
Hold Right Mouse Click + Move Trackball	Using "form" or "drop" tool	CHANGE THE SIZE OF THE TOOL AT HAND
<Space Bar>	EDIT MARGIN	CHANGE BETWEEN Hi-INTENSITY + VIRTUAL MODEL
<Ctrl> + <c>	DESIGN + MILL PREVIEW	CUT TOOL
<Ctrl> + <m>	DESIGN + MILL PREVIEW	MILL
<Ctrl> + <b>	DESIGN + MILL PREVIEW	VIRTURL FIT CHECKER (CHECK BINDING)
<Ctrl> + <>	MILLING PREVIEW (BLOCK SELECTION)	FAST MILL